APPENDIX 4 – WEIR MILL SITE PHOTOS



Current Condition from corner of Chestergate and King Street West.



Current Condition looking into courtyard from Chestergate



Current Condition from King Street West bridge.



Interior West Mill



Interior West Shed





Wheelhouse Roof



Interior East Mill