

Asset Management Programme - Appendix B

School	Project Description	Category	Estimated Cost including fees £000
Adswood Primary	Various works	Condition	680
Bolshaw Primary	Boiler Replacement	Condition	73
Cheadle Primary	Mechanical & Electrical – Block 2	Condition	111
Cheadle Primary	Roof – Block 2	Condition	137
Great Moor Infants	Rewire	Condition	305
Great Moor Juniors	Rewire	Condition	348
Greave Primary	Hydrogeology Works	Condition	293
Hazel Grove Primary	Mechanical & Electrical – Infant Block	Condition	215
Hazel Grove Primary	Roof – Infant Block	Condition	247
Ladybrook Primary	Fan Convector Replacement	Condition	57
St John's CE Primary	PSBP – Field Reinstatement	Condition	250 (includes 50 uplift)
Stockport School	Rewire	Condition	2,025
Stockport School	Repointing	Condition	320
Stockport School	Heating Works	Condition	220
Stockport School	Roofing Works	Condition	3,135
Stockport School	Mobile Replacement	Condition	800
Whitehill Primary	Fan Convector Replacement	Condition	48
		Total	9,264