

Affected area January 2021




February 2022 post storm deterioration





August 2023-shale bed undercut.



Barriers

Original as installed



As vandalised



Current barriers and signs



Aerial Views (top QGIS Aerial View 2009, bottom google maps 2023) showing mass of deposited material needing to be moved.

