2: DynoRod Report confirming root damage of drains





Customer Checklist Report

Your engineer is leaving you this checklist to help you understand the work we have carried out. They will also talk you through what they have done and any additional work which may be needed.

Name	Mr Fury	
Site		
Street 1	23 Offerton Road	
Street 2	Hazel Grove	
Street 3		
Postal Code	SK7 4NL	
City	STOCKPORT	

Booking number	DY-WO-3820819-2
Arrival time	31/01/2024 13:24
End time	31/01/2024 13:56
Type of work	Drains
Completed Status	Successful
Hazards identified?	Yes

Access required to	Yes	
facilitate the repair?		
Pre-existing Damage?	Yes	
Addition work required?	No	
Date of next visit		
TAN		

Resolution	Blocked toilet plunged and jetted from manhole from the front of the prop roots in the line jetted and restored for now this will need a root cut

Customer Signature

Resource Name David Logue