

Appendix F – Photos of Driveway

Evidence to support removal of TPO – 23 Offerton Road SK7 4NL

3: Photograph illustrating root damage to driveway – context



Evidence to support removal of TPO – 23 Offerton Road SK7 4NL

4: : Photograph illustrating root damage to driveway – closeup 1



Evidence to support removal of TPO – 23 Offerton Road SK7 4NL

5: Photograph illustrating root damage to driveway – closeup 2



Evidence to support removal of TPO – 23 Offerton Road SK7 4NL

6: Photograph illustrating root damage to driveway – closeup 2

